

REF: HPA/PMC-Safety Cert./128/23-24

Date: 22/08/2023

Building Safety Certificate

Name of the School: Trinity International School

Address : Sr. No 25 & 27 Pisoli, Tal – Haveli, Pune – Saswad Road, Near Bapdev
Ghat, Dist. – Pune 48.

I Certify that I have inspected the Building of the Trinity International School, at Sr. No.25 & 27 Block No ----, Village Pisoli, Taluka – Haveli owned by **KJ's Educational Institute** the plans of which have been approved by the Town Planning Dept. T. P. Vide their letter No. 4869 dated 20/08/2014.


I have done the Structural Audit based on the visual inspection on 17-08-2023, of the accessible parts/area of the building. Based on the visual observations, visual symptoms & manifestations shown by the structure and the data collected from site, I am the opinion that the said structure/building is structurally sound and that its stability will not be endangered by its use as a School building for which structure/building is intended. A detail Structural Audit Report covering details about structure, site observation along with photographic survey is attached with this certificate.

I hereby certify that **Trinity International School** is found safe structurally for the purpose of utility of building. This Certification is valid for a Period of One Year, from the date of Issue. That is valid till 29/08/2024.

For, **Hannsal Parikh & Associates,**

Mr. Hannsal S. Parikh
Registration No. – 97

Category: A



PRINCIPAL
Trinity International School



Manager
Trinity International School